

Detailed Test History



Test Status: All, Test Type: All
Person: All, Instrument: All
From: 11/06/2013 To: 10/06/2014

Client: DiscoCo.com	Site: 70 CANTERBURY	Location: DURHAM		
Asset ID: 001	Description: EURO	User: USER 4	Test Instrument: Y42-0708	
Test Type	Date	Result	Unit	Status
Visual	11/06/2013			Pass
Earth Current	11/06/2013	25	A	Information
Earth	11/06/2013	0.08	Ohm	Pass
Insulation	11/06/2013	>99.99	MOhm	Pass
Polarity	11/06/2013			Pass
Overall: Pass				
Asset ID: 002	Description: EURO	User: USER 4	Test Instrument: Y42-0708	
Test Type	Date	Result	Unit	Status
Visual	11/06/2013			Pass
Earth Current	11/06/2013	25	A	Information
Earth	11/06/2013	0.09	Ohm	Pass
Insulation	11/06/2013	>99.99	MOhm	Pass
Polarity	11/06/2013			Pass
Overall: Pass				
Asset ID: 003	Description: EURO	User: USER 4	Test Instrument: Y42-0708	
Test Type	Date	Result	Unit	Status
Visual	11/06/2013			Pass
Earth Current	11/06/2013	25	A	Information
Earth	11/06/2013	0.06	Ohm	Pass
Insulation	11/06/2013	>99.99	MOhm	Pass
Polarity	11/06/2013			Pass
Overall: Pass				
Asset ID: 004	Description: EURO	User: USER 4	Test Instrument: Y42-0708	
Test Type	Date	Result	Unit	Status
Visual	11/06/2013			Pass
Earth Current	11/06/2013	25	A	Information
Earth	11/06/2013	0.06	Ohm	Pass
Insulation	11/06/2013	>99.99	MOhm	Pass
Polarity	11/06/2013			Pass
Overall: Pass				
Asset ID: 005	Description: EURO	User: USER 4	Test Instrument: Y42-0708	
Test Type	Date	Result	Unit	Status
Visual	11/06/2013			Pass
Earth Current	11/06/2013	25	A	Information
Earth	11/06/2013	0.07	Ohm	Pass
Insulation	11/06/2013	>99.99	MOhm	Pass
Polarity	11/06/2013			Pass
Overall: Pass				
Asset ID: 006	Description: EURO	User: USER 4	Test Instrument: Y42-0708	
Test Type	Date	Result	Unit	Status
Visual	11/06/2013			Pass
Earth Current	11/06/2013	25	A	Information
Earth	11/06/2013	0.04	Ohm	Pass
Insulation	11/06/2013	>99.99	MOhm	Pass
Polarity	11/06/2013			Pass
Overall: Pass				
Asset ID: 007	Description: EURO EXT	User: USER 4	Test Instrument: Y42-0708	
Test Type	Date	Result	Unit	Status
Visual	11/06/2013			Pass
Earth Current	11/06/2013	25	A	Information
Earth	11/06/2013	0.26	Ohm	Pass
Insulation	11/06/2013	>99.99	MOhm	Pass
Polarity	11/06/2013			Pass
Overall: Pass				
Asset ID: 008	Description: EURO EXT	User: USER 4	Test Instrument: Y42-0708	
Test Type	Date	Result	Unit	Status
Visual	11/06/2013			Pass
Earth Current	11/06/2013	25	A	Information
Earth	11/06/2013	0.17	Ohm	Pass
Insulation	11/06/2013	>99.99	MOhm	Pass
Polarity	11/06/2013			Pass

Detailed Test History



Test Status: All, Test Type: All
Person: All, Instrument: All
From: 11/06/2013 To: 10/06/2014

Overall: Pass

Asset ID: 009	Description: POWER PACK	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Earth Current	11/06/2013	25	A Information
Earth	11/06/2013	0.19	Ohm Pass
Insulation	11/06/2013	>99.99	MOhm Pass
Polarity	11/06/2013		Pass

Overall: Pass

Asset ID: 010	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Earth Current	11/06/2013	25	A Information
Earth	11/06/2013	0.24	Ohm Pass
Insulation	11/06/2013	>99.99	MOhm Pass
Polarity	11/06/2013		Pass

Overall: Pass

Asset ID: 011	Description: EXT	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Earth Current	11/06/2013	25	A Information
Earth	11/06/2013	0.07	Ohm Pass
Insulation	11/06/2013	>99.99	MOhm Pass
Polarity	11/06/2013		Pass

Overall: Pass

Asset ID: 012	Description: EXT	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Earth Current	11/06/2013	25	A Information
Earth	11/06/2013	0.06	Ohm Pass
Insulation	11/06/2013	>99.99	MOhm Pass
Polarity	11/06/2013		Pass

Overall: Pass

Asset ID: 013	Description: EXT	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Earth Current	11/06/2013	25	A Information
Earth	11/06/2013	0.07	Ohm Pass
Insulation	11/06/2013	>99.99	MOhm Pass
Polarity	11/06/2013		Pass

Overall: Pass

Asset ID: 014	Description: DYNAMO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Earth Current	11/06/2013	25	A Information
Earth	11/06/2013	0.06	Ohm Pass
Insulation	11/06/2013	>99.99	MOhm Pass
Leakage	11/06/2013	<0.1	mA Pass
Load	11/06/2013	<0.05	kVA Information

Overall: Pass

Asset ID: 015	Description: DYNAMO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Earth Current	11/06/2013	25	A Information
Earth	11/06/2013	0.06	Ohm Pass
Insulation	11/06/2013	>99.99	MOhm Pass
Leakage	11/06/2013	<0.1	mA Pass
Load	11/06/2013	<0.05	kVA Information

Overall: Pass

Asset ID: 016	Description: DYNAMO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Earth Current	11/06/2013	25	A Information
Earth	11/06/2013	0.06	Ohm Pass

Detailed Test History



Test Status: All, Test Type: All
Person: All, Instrument: All
From: 11/06/2013 To: 10/06/2014

Insulation	11/06/2013	>99.99	MOhm	Pass
Leakage	11/06/2013	<0.1	mA	Pass
Load	11/06/2013	<0.05	kVA	Information

Overall: Pass

Asset ID: 017	Description: DYNAMO	User: USER 4	Test Instrument: Y42-0708
---------------	---------------------	--------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	11/06/2013			Pass
Earth Current	11/06/2013	25	A	Information
Earth	11/06/2013	0.06	Ohm	Pass
Insulation	11/06/2013	>99.99	MOhm	Pass
Leakage	11/06/2013	<0.1	mA	Pass
Load	11/06/2013	<0.05	kVA	Information

Overall: Pass

Asset ID: 018	Description: SPEAKER	User: USER 4	Test Instrument: Y42-0708
---------------	----------------------	--------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	11/06/2013			Pass
Earth Current	11/06/2013	25	A	Information
Earth	11/06/2013	0.06	Ohm	Pass
Insulation	11/06/2013	>99.99	MOhm	Pass
Leakage	11/06/2013	<0.1	mA	Pass
Load	11/06/2013	<0.05	kVA	Information

Overall: Pass

Asset ID: 019	Description: SPEAKER	User: USER 4	Test Instrument: Y42-0708
---------------	----------------------	--------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	11/06/2013			Pass
Earth Current	11/06/2013	25	A	Information
Earth	11/06/2013	0.06	Ohm	Pass
Insulation	11/06/2013	>99.99	MOhm	Pass
Leakage	11/06/2013	<0.1	mA	Pass
Load	11/06/2013	<0.05	kVA	Information

Overall: Pass

Asset ID: 020	Description: SMOKE MACHINE	User: USER 4	Test Instrument: Y42-0708
---------------	----------------------------	--------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	11/06/2013			Pass
Earth Current	11/06/2013	25	A	Information
Earth	11/06/2013	0.04	Ohm	Pass
Insulation	11/06/2013	>99.99	MOhm	Pass
Leakage	11/06/2013	<0.1	mA	Pass
Load	11/06/2013	<0.05	kVA	Information

Overall: Pass

Asset ID: 021	Description: CD PLAYER	User: USER 4	Test Instrument: Y42-0708
---------------	------------------------	--------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	11/06/2013			Pass
Insulation	11/06/2013	>99.99	MOhm	Pass
Touch Leakage	11/06/2013	<0.1	mA	Pass

Overall: Pass

Asset ID: 022	Description: MIXER	User: USER 4	Test Instrument: Y42-0708
---------------	--------------------	--------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	11/06/2013			Pass
Insulation	11/06/2013	>99.99	MOhm	Pass
Touch Leakage	11/06/2013	<0.1	mA	Pass

Overall: Pass

Asset ID: 023	Description: FX LIGHT	User: USER 4	Test Instrument: Y42-0708
---------------	-----------------------	--------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	11/06/2013			Pass
Earth Current	11/06/2013	100	mA a.c.	Information
Earth	11/06/2013	0.06	Ohm	Pass
Insulation	11/06/2013	>99.99	MOhm	Pass

Overall: Pass

Asset ID: 024	Description: TRICLOPS	User: USER 4	Test Instrument: Y42-0708
---------------	-----------------------	--------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	11/06/2013			Pass
Insulation	11/06/2013	>99.99	MOhm	Pass

Detailed Test History



Test Status: All, Test Type: All
Person: All, Instrument: All
From: 11/06/2013 To: 10/06/2014

Overall: Pass

Asset ID: 042	Description: EXT	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Earth Current	11/06/2013	25	A Information
Earth	11/06/2013	0.09	Ohm Pass
Insulation	11/06/2013	>99.99	MOhm Pass
Polarity	11/06/2013		Pass

Overall: Pass

Asset ID: 043	Description: EXT	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Earth Current	11/06/2013	25	A Information
Earth	11/06/2013	0.09	Ohm Pass
Insulation	11/06/2013	>99.99	MOhm Pass
Polarity	11/06/2013		Pass

Overall: Pass

Asset ID: 044	Description: POWER PACK	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Earth Current	11/06/2013	25	A Information
Earth	11/06/2013	0.18	Ohm Pass
Insulation	11/06/2013	>99.99	MOhm Pass
Polarity	11/06/2013		Pass

Overall: Pass

Asset ID: 060	Description: EXT	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Earth Current	11/06/2013	25	A Information
Earth	11/06/2013	0.07	Ohm Pass
Insulation	11/06/2013	>99.99	MOhm Pass
Polarity	11/06/2013		Pass

Overall: Pass

Asset ID: 061	Description: EXT	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Earth Current	11/06/2013	25	A Information
Earth	11/06/2013	0.08	Ohm Pass
Insulation	11/06/2013	>99.99	MOhm Pass
Polarity	11/06/2013		Pass

Overall: Pass

Asset ID: 062	Description: POWER PACK	User:	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Earth	15/06/2013	0.06	Ohms Pass
Insulation	15/06/2013	>99.99	MOhms Pass
Touch Leakage	15/06/2013	0.10	mA Pass

Overall: Pass

Asset ID: 062	Description: POWER PACK	User: Admin	Test Instrument:
Test Type	Date	Result	Unit Status
Visual	15/06/2013		Pass

Overall: Pass

Asset ID: 063	Description: EXT	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Earth Current	11/06/2013	25	A Information
Earth	11/06/2013	0.43	Ohm Pass
Insulation	11/06/2013	>99.99	MOhm Pass
Polarity	11/06/2013		Pass

Overall: Pass

Asset ID: 064	Description: EXT	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Earth Current	11/06/2013	25	A Information

Detailed Test History



Test Status: All, Test Type: All
Person: All, Instrument: All
From: 11/06/2013 To: 10/06/2014

Earth	11/06/2013	0.45	Ohm	Pass
Insulation	11/06/2013	>99.99	MOhm	Pass
Polarity	11/06/2013			Pass

Overall: Pass

Asset ID: 065	Description: EXTEXT	User: USER 4	Test Instrument: Y42-0708
---------------	---------------------	--------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	11/06/2013			Pass
Earth Current	11/06/2013	25	A	Information
Earth	11/06/2013	0.45	Ohm	Pass
Insulation	11/06/2013	>99.99	MOhm	Pass
Polarity	11/06/2013			Pass

Overall: Pass

Asset ID: 066	Description: TRICLOPS	User: USER 4	Test Instrument: Y42-0708
---------------	-----------------------	--------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	11/06/2013			Pass
Insulation	11/06/2013	>99.99	MOhm	Pass

Overall: Pass

Asset ID: 070	Description: TRICLOPS	User: USER 4	Test Instrument: Y42-0708
---------------	-----------------------	--------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	11/06/2013			Pass
Insulation	11/06/2013	>99.99	MOhm	Pass

Overall: Pass

Asset ID: 071	Description: GTS FX LIGHT	User: USER 4	Test Instrument: Y42-0708
---------------	---------------------------	--------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	11/06/2013			Pass
Earth Current	11/06/2013	100	mA a.c.	Information
Earth	11/06/2013	0.05	Ohm	Pass
Insulation	11/06/2013	>99.99	MOhm	Pass

Overall: Pass

Asset ID: 072	Description: GTX FX LIGHT	User: USER 4	Test Instrument: Y42-0708
---------------	---------------------------	--------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	11/06/2013			Pass
Earth Current	11/06/2013	100	mA a.c.	Information
Earth	11/06/2013	0.06	Ohm	Pass
Insulation	11/06/2013	>99.99	MOhm	Pass

Overall: Pass

Asset ID: 073	Description: SPEAKER	User: USER 4	Test Instrument: Y42-0708
---------------	----------------------	--------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	11/06/2013			Pass
Earth Current	11/06/2013	100	mA a.c.	Information
Earth	11/06/2013	0.05	Ohm	Pass
Insulation	11/06/2013	>99.99	MOhm	Pass

Overall: Pass

Asset ID: 074	Description: SPEAKER	User: USER 4	Test Instrument: Y42-0708
---------------	----------------------	--------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	11/06/2013			Pass
Earth Current	11/06/2013	100	mA a.c.	Information
Earth	11/06/2013	0.07	Ohm	Pass
Insulation	11/06/2013	>99.99	MOhm	Pass

Overall: Pass

Asset ID: 075	Description: SPEAKER	User: USER 4	Test Instrument: Y42-0708
---------------	----------------------	--------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	11/06/2013			Pass
Earth Current	11/06/2013	100	mA a.c.	Information
Earth	11/06/2013	0.07	Ohm	Pass
Insulation	11/06/2013	>99.99	MOhm	Pass

Overall: Pass

Asset ID: 076	Description: SPEAKER	User: USER 4	Test Instrument: Y42-0708
---------------	----------------------	--------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	11/06/2013			Pass
Earth Current	11/06/2013	100	mA a.c.	Information
Earth	11/06/2013	0.07	Ohm	Pass
Insulation	11/06/2013	>99.99	MOhm	Pass

Detailed Test History



Test Status: All, Test Type: All
Person: All, Instrument: All
From: 11/06/2013 To: 10/06/2014

Overall: Pass

Asset ID: 077	Description: SPEAKER	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Earth Current	11/06/2013	100	mA a.c. Information
Earth	11/06/2013	0.06	Ohm Pass
Insulation	11/06/2013	>99.99	MOhm Pass

Overall: Pass

Asset ID: 078	Description: SPEAKER	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Earth Current	11/06/2013	100	mA a.c. Information
Earth	11/06/2013	0.06	Ohm Pass
Insulation	11/06/2013	>99.99	MOhm Pass

Overall: Pass

Asset ID: 079	Description: DYNAMO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Earth Current	11/06/2013	100	mA a.c. Information
Earth	11/06/2013	0.06	Ohm Pass
Insulation	11/06/2013	>99.99	MOhm Pass

Overall: Pass

Asset ID: 080	Description: DYNAMO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Earth Current	11/06/2013	100	mA a.c. Information
Earth	11/06/2013	0.04	Ohm Pass
Insulation	11/06/2013	>99.99	MOhm Pass

Overall: Pass

Asset ID: 081	Description: DYNAMO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Earth Current	11/06/2013	100	mA a.c. Information
Earth	11/06/2013	0.07	Ohm Pass
Insulation	11/06/2013	>99.99	MOhm Pass

Overall: Pass

Asset ID: 082	Description: DYNAMO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Earth Current	11/06/2013	100	mA a.c. Information
Earth	11/06/2013	0.04	Ohm Pass
Insulation	11/06/2013	>99.99	MOhm Pass

Overall: Pass

Asset ID: 083	Description: DYNAMO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Earth Current	11/06/2013	100	mA a.c. Information
Earth	11/06/2013	0.04	Ohm Pass
Insulation	11/06/2013	>99.99	MOhm Pass

Overall: Pass

Asset ID: 084	Description: DYNAMO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Earth Current	11/06/2013	100	mA a.c. Information
Earth	11/06/2013	0.04	Ohm Pass
Insulation	11/06/2013	>99.99	MOhm Pass

Overall: Pass

Asset ID: 085	Description: DYNAMO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Earth Current	11/06/2013	100	mA a.c. Information
Earth	11/06/2013	0.04	Ohm Pass
Insulation	11/06/2013	>99.99	MOhm Pass

Detailed Test History



Test Status: All, Test Type: All
Person: All, Instrument: All
From: 11/06/2013 To: 10/06/2014

Overall: Pass

Asset ID: 086	Description: DYNAMO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Earth Current	11/06/2013	100	mA a.c. Information
Earth	11/06/2013	0.04	Ohm Pass
Insulation	11/06/2013	>99.99	MOhm Pass

Overall: Pass

Asset ID: 087	Description: DYNAMO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Earth Current	11/06/2013	100	mA a.c. Information
Earth	11/06/2013	0.05	Ohm Pass
Insulation	11/06/2013	>99.99	MOhm Pass

Overall: Pass

Asset ID: 088	Description: DYNAMO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Earth Current	11/06/2013	100	mA a.c. Information
Earth	11/06/2013	0.05	Ohm Pass
Insulation	11/06/2013	>99.99	MOhm Pass

Overall: Pass

Asset ID: 089	Description: DYNAMO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Earth Current	11/06/2013	100	mA a.c. Information
Earth	11/06/2013	0.04	Ohm Pass
Insulation	11/06/2013	>99.99	MOhm Pass

Overall: Pass

Asset ID: 090	Description: DYNAMO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Earth Current	11/06/2013	100	mA a.c. Information
Earth	11/06/2013	0.04	Ohm Pass
Insulation	11/06/2013	>99.99	MOhm Pass

Overall: Pass

Asset ID: 091	Description: CD PLAYER	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Insulation	11/06/2013	>99.99	MOhm Pass

Overall: Pass

Asset ID: 092	Description: MIXER	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Insulation	11/06/2013	>99.99	MOhm Pass

Overall: Pass

Asset ID: 093	Description: MIXER	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Insulation	11/06/2013	>99.99	MOhm Pass

Overall: Pass

Asset ID: 094	Description: CD PLAYER	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Insulation	11/06/2013	>99.99	MOhm Pass

Overall: Pass

Asset ID: 095	Description: EXT	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Earth Current	11/06/2013	25	A Information
Earth	11/06/2013	0.13	Ohm Pass
Insulation	11/06/2013	>99.99	MOhm Pass

Detailed Test History



Test Status: All, Test Type: All
Person: All, Instrument: All
From: 11/06/2013 To: 10/06/2014

Polarity 11/06/2013 Pass
Overall: Pass

Asset ID: 096	Description: EXT	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Earth Current	11/06/2013	25	A Information
Earth	11/06/2013	0.07	Ohm Pass
Insulation	11/06/2013	>99.99	MOhm Pass
Polarity	11/06/2013		Pass

Overall: Pass

Asset ID: 097	Description: IEC	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	Ohm Pass
Insulation	12/06/2013	>99.99	MOhm Pass
Polarity	12/06/2013		Pass

Overall: Pass

Asset ID: 098	Description: IEC	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	Ohm Pass
Insulation	12/06/2013	>99.99	MOhm Pass
Polarity	12/06/2013		Pass

Overall: Pass

Asset ID: 099	Description: IEC	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	Ohm Pass
Insulation	12/06/2013	>99.99	MOhm Pass
Polarity	12/06/2013		Pass

Overall: Pass

Asset ID: 100	Description: IEC	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	Ohm Pass
Insulation	12/06/2013	>99.99	MOhm Pass
Polarity	12/06/2013		Pass

Overall: Pass

Asset ID: 101	Description: IEC	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	Ohm Pass
Insulation	12/06/2013	>99.99	MOhm Pass
Polarity	12/06/2013		Pass

Overall: Pass

Asset ID: 102	Description: IEC	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	Ohm Pass
Insulation	12/06/2013	>99.99	MOhm Pass
Polarity	12/06/2013		Pass

Overall: Pass

Asset ID: 103	Description: IEC	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	Ohm Pass
Insulation	12/06/2013	>99.99	MOhm Pass

Detailed Test History



Test Status: All, Test Type: All
Person: All, Instrument: All
From: 11/06/2013 To: 10/06/2014

Polarity 12/06/2013 Pass
Overall: Pass

Asset ID: 104	Description: IEC	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	Ohm Pass
Insulation	12/06/2013	>99.99	MOhm Pass
Polarity	12/06/2013		Pass
Overall: Pass			

Asset ID: 105	Description: IEC	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	Ohm Pass
Insulation	12/06/2013	>99.99	MOhm Pass
Polarity	12/06/2013		Pass
Overall: Pass			

Asset ID: 106	Description: IEC	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	Ohm Pass
Insulation	12/06/2013	>99.99	MOhm Pass
Polarity	12/06/2013		Pass
Overall: Pass			

Asset ID: 107	Description: IEC	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	Ohm Pass
Insulation	12/06/2013	>99.99	MOhm Pass
Polarity	12/06/2013		Pass
Overall: Pass			

Asset ID: 108	Description: IEC	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	Ohm Pass
Insulation	12/06/2013	>99.99	MOhm Pass
Polarity	12/06/2013		Pass
Overall: Pass			

Asset ID: 109	Description: IEC	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	Ohm Pass
Insulation	12/06/2013	>99.99	MOhm Pass
Polarity	12/06/2013		Pass
Overall: Pass			

Asset ID: 110	Description: IEC	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	Ohm Pass
Insulation	12/06/2013	>99.99	MOhm Pass
Polarity	12/06/2013		Pass
Overall: Pass			

Asset ID: 111	Description: IEC	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	Ohm Pass
Insulation	12/06/2013	>99.99	MOhm Pass

Detailed Test History



Test Status: All, Test Type: All
Person: All, Instrument: All
From: 11/06/2013 To: 10/06/2014

Polarity 12/06/2013 Pass
Overall: Pass

Asset ID: 112	Description: IEC	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	Ohm Pass
Insulation	12/06/2013	>99.99	MOhm Pass
Polarity	12/06/2013		Pass
Overall: Pass			

Asset ID: 113	Description: IEC	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	Ohm Pass
Insulation	12/06/2013	>99.99	MOhm Pass
Polarity	12/06/2013		Pass
Overall: Pass			

Asset ID: 114	Description: IEC	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	Ohm Pass
Insulation	12/06/2013	>99.99	MOhm Pass
Polarity	12/06/2013		Pass
Overall: Pass			

Asset ID: 115	Description: IEC	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	Ohm Pass
Insulation	12/06/2013	>99.99	MOhm Pass
Polarity	12/06/2013		Pass
Overall: Pass			

Asset ID: 116	Description: IEC	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	Ohm Pass
Insulation	12/06/2013	>99.99	MOhm Pass
Polarity	12/06/2013		Pass
Overall: Pass			

Asset ID: 117	Description: IEC	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	Ohm Pass
Insulation	12/06/2013	>99.99	MOhm Pass
Polarity	12/06/2013		Pass
Overall: Pass			

Asset ID: 118	Description: IEC	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	Ohm Pass
Insulation	12/06/2013	>99.99	MOhm Pass
Polarity	12/06/2013		Pass
Overall: Pass			

Asset ID: 119	Description: IEC	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	Ohm Pass
Insulation	12/06/2013	>99.99	MOhm Pass

Detailed Test History



Test Status: All, Test Type: All
Person: All, Instrument: All
From: 11/06/2013 To: 10/06/2014

Polarity 12/06/2013 Pass
Overall: Pass

Asset ID: 120	Description: IEC	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	Ohm Pass
Insulation	12/06/2013	>99.99	MOhm Pass
Polarity	12/06/2013		Pass
Overall: Pass			

Asset ID: 121	Description: IEC	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	Ohm Pass
Insulation	12/06/2013	>99.99	MOhm Pass
Polarity	12/06/2013		Pass
Overall: Pass			

Asset ID: 122	Description: IEC	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	Ohm Pass
Insulation	12/06/2013	>99.99	MOhm Pass
Polarity	12/06/2013		Pass
Overall: Pass			

Asset ID: 123	Description: IEC	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	Ohm Pass
Insulation	12/06/2013	>99.99	MOhm Pass
Polarity	12/06/2013		Pass
Overall: Pass			

Asset ID: 124	Description: IEC	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	Ohm Pass
Insulation	12/06/2013	>99.99	MOhm Pass
Polarity	12/06/2013		Pass
Overall: Pass			

Asset ID: 125	Description: IEC	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	Ohm Pass
Insulation	12/06/2013	>99.99	MOhm Pass
Polarity	12/06/2013		Pass
Overall: Pass			

Asset ID: 126	Description: IEC	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	Ohm Pass
Insulation	12/06/2013	>99.99	MOhm Pass
Polarity	12/06/2013		Pass
Overall: Pass			

Asset ID: 127	Description: IEC	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	Ohm Pass
Insulation	12/06/2013	>99.99	MOhm Pass

Detailed Test History



Test Status: All, Test Type: All
Person: All, Instrument: All
From: 11/06/2013 To: 10/06/2014

Polarity 12/06/2013 Pass
Overall: Pass

Asset ID: 128	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	Ohm Pass
Insulation	12/06/2013	>99.99	MOhm Pass
Polarity	12/06/2013		Pass
Overall: Pass			

Asset ID: 129	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	Ohm Pass
Insulation	12/06/2013	>99.99	MOhm Pass
Polarity	12/06/2013		Pass
Overall: Pass			

Asset ID: 130	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	Ohm Pass
Insulation	12/06/2013	>99.99	MOhm Pass
Polarity	12/06/2013		Pass
Overall: Pass			

Asset ID: 131	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	Ohm Pass
Insulation	12/06/2013	>99.99	MOhm Pass
Polarity	12/06/2013		Pass
Overall: Pass			

Asset ID: 132	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	Ohm Pass
Insulation	12/06/2013	>99.99	MOhm Pass
Polarity	12/06/2013		Pass
Overall: Pass			

Asset ID: 133	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	Ohm Pass
Insulation	12/06/2013	>99.99	MOhm Pass
Polarity	12/06/2013		Pass
Overall: Pass			

Asset ID: 134	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	Ohm Pass
Insulation	12/06/2013	>99.99	MOhm Pass
Polarity	12/06/2013		Pass
Overall: Pass			

Asset ID: 135	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	Ohm Pass
Insulation	12/06/2013	>99.99	MOhm Pass

Detailed Test History



Test Status: All, Test Type: All
Person: All, Instrument: All
From: 11/06/2013 To: 10/06/2014

Polarity 12/06/2013 Pass
Overall: Pass

Asset ID: 136	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	Ohm Pass
Insulation	12/06/2013	>99.99	MOhm Pass
Polarity	12/06/2013		Pass
Overall: Pass			

Asset ID: 137	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	Ohm Pass
Insulation	12/06/2013	>99.99	MOhm Pass
Polarity	12/06/2013		Pass
Overall: Pass			

Asset ID: 138	Description: IEC	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	Ohm Pass
Insulation	12/06/2013	>99.99	MOhm Pass
Polarity	12/06/2013		Pass
Overall: Pass			

Asset ID: 139	Description: IEC	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	Ohm Pass
Insulation	12/06/2013	>99.99	MOhm Pass
Polarity	12/06/2013		Pass
Overall: Pass			

Asset ID: 140	Description: IEC	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	Ohm Pass
Insulation	12/06/2013	>99.99	MOhm Pass
Polarity	12/06/2013		Pass
Overall: Pass			

Asset ID: 141	Description: IEC	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	Ohm Pass
Insulation	12/06/2013	>99.99	MOhm Pass
Polarity	12/06/2013		Pass
Overall: Pass			

Asset ID: 142	Description: IEC	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	Ohm Pass
Insulation	12/06/2013	>99.99	MOhm Pass
Polarity	12/06/2013		Pass
Overall: Pass			

Asset ID: 143	Description: IEC	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	Ohm Pass
Insulation	12/06/2013	>99.99	MOhm Pass

Detailed Test History



Test Status: All, Test Type: All
Person: All, Instrument: All
From: 11/06/2013 To: 10/06/2014

Polarity 12/06/2013 Pass
Overall: Pass

Asset ID: 144	Description: IEC	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	Ohm Pass
Insulation	12/06/2013	>99.99	MOhm Pass
Polarity	12/06/2013		Pass
Overall: Pass			

Asset ID: 145	Description: IEC	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	Ohm Pass
Insulation	12/06/2013	>99.99	MOhm Pass
Polarity	12/06/2013		Pass
Overall: Pass			

Asset ID: 146	Description: IEC	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	Ohm Pass
Insulation	12/06/2013	>99.99	MOhm Pass
Polarity	12/06/2013		Pass
Overall: Pass			

Asset ID: 147	Description: IEC	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	Ohm Pass
Insulation	12/06/2013	>99.99	MOhm Pass
Polarity	12/06/2013		Pass
Overall: Pass			

Asset ID: 148	Description: IEC	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	Ohm Pass
Insulation	12/06/2013	>99.99	MOhm Pass
Polarity	12/06/2013		Pass
Overall: Pass			

Asset ID: 149	Description: IEC	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	Ohm Pass
Insulation	12/06/2013	>99.99	MOhm Pass
Polarity	12/06/2013		Pass
Overall: Pass			

Asset ID: 162	Description: SPEAKER	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Earth Current	11/06/2013	100	mA a.c. Information
Earth	11/06/2013	0.04	Ohm Pass
Insulation	11/06/2013	>99.99	MOhm Pass
Overall: Pass			

Asset ID: 163	Description: SPEAKER	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Earth Current	11/06/2013	100	mA a.c. Information
Earth	11/06/2013	0.04	Ohm Pass
Insulation	11/06/2013	>99.99	MOhm Pass

Detailed Test History



Test Status: All, Test Type: All
Person: All, Instrument: All
From: 11/06/2013 To: 10/06/2014

Overall: Pass

Asset ID: 164	Description: SPEAKER	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Earth Current	11/06/2013	100	mA a.c. Information
Earth	11/06/2013	0.04	Ohm Pass
Insulation	11/06/2013	>99.99	MOhm Pass

Overall: Pass

Asset ID: 165	Description: SPEAKER	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Earth Current	11/06/2013	100	mA a.c. Information
Earth	11/06/2013	<0.04	Ohm Pass
Insulation	11/06/2013	>99.99	MOhm Pass

Overall: Pass

Asset ID: 166	Description: SPEAKER	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Earth Current	11/06/2013	100	mA a.c. Information
Earth	11/06/2013	<0.04	Ohm Pass
Insulation	11/06/2013	>99.99	MOhm Pass

Overall: Pass

Asset ID: 167	Description: SPEAKER	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Earth Current	11/06/2013	100	mA a.c. Information
Earth	11/06/2013	<0.04	Ohm Pass
Insulation	11/06/2013	>99.99	MOhm Pass

Overall: Pass

Asset ID: 168	Description: SPEAKER	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Earth Current	11/06/2013	100	mA a.c. Information
Earth	11/06/2013	<0.04	Ohm Pass
Insulation	11/06/2013	>99.99	MOhm Pass

Overall: Pass

Asset ID: 169	Description: SPEAKER	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Earth Current	11/06/2013	100	mA a.c. Information
Earth	11/06/2013	<0.04	Ohm Pass
Insulation	11/06/2013	>99.99	MOhm Pass

Overall: Pass

Asset ID: 170	Description: SPEAKER	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Earth Current	11/06/2013	100	mA a.c. Information
Earth	11/06/2013	<0.04	Ohm Pass
Insulation	11/06/2013	>99.99	MOhm Pass

Overall: Pass

Asset ID: 171	Description: SPEAKER	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Earth Current	11/06/2013	100	mA a.c. Information
Earth	11/06/2013	<0.04	Ohm Pass
Insulation	11/06/2013	>99.99	MOhm Pass

Overall: Pass

Asset ID: 172	Description: SPEAKER	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Earth Current	11/06/2013	100	mA a.c. Information
Earth	11/06/2013	<0.04	Ohm Pass
Insulation	11/06/2013	>99.99	MOhm Pass

Detailed Test History



Test Status: All, Test Type: All
Person: All, Instrument: All
From: 11/06/2013 To: 10/06/2014

Overall: Pass

Asset ID: 173	Description: SPEAKER	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Earth Current	11/06/2013	100	mA a.c. Information
Earth	11/06/2013	<0.04	Ohm Pass
Insulation	11/06/2013	>99.99	MOhm Pass

Overall: Pass

Asset ID: 174	Description: SPEAKER	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Earth Current	11/06/2013	100	mA a.c. Information
Earth	11/06/2013	<0.04	Ohm Pass
Insulation	11/06/2013	>99.99	MOhm Pass

Overall: Pass

Asset ID: 175	Description: SPEAKER	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Earth Current	11/06/2013	100	mA a.c. Information
Earth	11/06/2013	<0.04	Ohm Pass
Insulation	11/06/2013	>99.99	MOhm Pass

Overall: Pass

Asset ID: 176	Description: SPEAKER	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Earth Current	11/06/2013	100	mA a.c. Information
Earth	11/06/2013	<0.04	Ohm Pass
Insulation	11/06/2013	>99.99	MOhm Pass

Overall: Pass

Asset ID: 177	Description: CD PLAYER	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Insulation	11/06/2013	>99.99	MOhm Pass

Overall: Pass

Asset ID: 178	Description: MIXER	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Earth Current	11/06/2013	100	mA a.c. Information
Earth	11/06/2013	<0.04	Ohm Pass
Insulation	11/06/2013	>99.99	MOhm Pass

Overall: Pass

Asset ID: 179	Description: MIXER	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Earth Current	11/06/2013	100	mA a.c. Information
Earth	11/06/2013	<0.04	Ohm Pass
Insulation	11/06/2013	>99.99	MOhm Pass

Overall: Pass

Asset ID: 180	Description: CD PLAYER	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Insulation	11/06/2013	>99.99	MOhm Pass

Overall: Pass

Asset ID: 181	Description: CD PLAYER	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Insulation	11/06/2013	>99.99	MOhm Pass

Overall: Pass

Asset ID: 182	Description: MIXER	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Earth Current	11/06/2013	100	mA a.c. Information

Detailed Test History



Test Status: All, Test Type: All
Person: All, Instrument: All
From: 11/06/2013 To: 10/06/2014

Earth	11/06/2013	0.04	Ohm	Pass
Insulation	11/06/2013	>99.99	MOhm	Pass

Overall: Pass

Asset ID: 183	Description: TRICLOPS	User: USER 4	Test Instrument: Y42-0708
---------------	-----------------------	--------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	11/06/2013			Pass
Earth Current	11/06/2013	4	A	Information
Earth	11/06/2013	0.1	Ohm	Pass
Insulation	11/06/2013	>99.99	MOhm	Pass
Leakage	11/06/2013	<0.1	mA	Pass
Load	11/06/2013	<0.05	kVA	Information

Overall: Pass

Asset ID: 184	Description: TRICLOPS	User: USER 4	Test Instrument: Y42-0708
---------------	-----------------------	--------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	11/06/2013			Pass
Earth Current	11/06/2013	4	A	Information
Earth	11/06/2013	0.13	Ohm	Pass
Insulation	11/06/2013	>99.99	MOhm	Pass
Leakage	11/06/2013	<0.1	mA	Pass
Load	11/06/2013	<0.05	kVA	Information

Overall: Pass

Asset ID: 185	Description: TRICLOPS	User: USER 4	Test Instrument: Y42-0708
---------------	-----------------------	--------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	11/06/2013			Pass
Earth Current	11/06/2013	4	A	Information
Earth	11/06/2013	0.18	Ohm	Pass
Insulation	11/06/2013	>99.99	MOhm	Pass
Leakage	11/06/2013	<0.1	mA	Pass
Load	11/06/2013	<0.05	kVA	Information

Overall: Pass

Asset ID: 186	Description: TRICLOPS	User: USER 4	Test Instrument: Y42-0708
---------------	-----------------------	--------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	11/06/2013			Pass
Earth Current	11/06/2013	4	A	Information
Earth	11/06/2013	0.11	Ohm	Pass
Insulation	11/06/2013	>99.99	MOhm	Pass
Leakage	11/06/2013	<0.1	mA	Pass
Load	11/06/2013	<0.05	kVA	Information

Overall: Pass

Asset ID: 187	Description: TRICLOPS	User: USER 4	Test Instrument: Y42-0708
---------------	-----------------------	--------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	11/06/2013			Pass
Earth Current	11/06/2013	4	A	Information
Earth	11/06/2013	0.13	Ohm	Pass
Insulation	11/06/2013	>99.99	MOhm	Pass
Leakage	11/06/2013	<0.1	mA	Pass
Load	11/06/2013	<0.05	kVA	Information

Overall: Pass

Asset ID: 188	Description: TRICLOPS	User: USER 4	Test Instrument: Y42-0708
---------------	-----------------------	--------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	11/06/2013			Pass
Earth Current	11/06/2013	4	A	Information
Earth	11/06/2013	0.12	Ohm	Pass
Insulation	11/06/2013	>99.99	MOhm	Pass
Leakage	11/06/2013	<0.1	mA	Pass
Load	11/06/2013	<0.05	kVA	Information

Overall: Pass

Asset ID: 189	Description: TRICLOPS	User: USER 4	Test Instrument: Y42-0708
---------------	-----------------------	--------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	11/06/2013			Pass
Earth Current	11/06/2013	4	A	Information
Earth	11/06/2013	0.12	Ohm	Pass
Insulation	11/06/2013	>99.99	MOhm	Pass
Leakage	11/06/2013	<0.1	mA	Pass
Load	11/06/2013	<0.05	kVA	Information

Detailed Test History



Test Status: All, Test Type: All
Person: All, Instrument: All
From: 11/06/2013 To: 10/06/2014

Overall: Pass

Asset ID: 190	Description: TRICLOPS	User: USER 4	Test Instrument: Y42-0708	
Test Type	Date	Result	Unit	Status
Visual	11/06/2013			Pass
Earth Current	11/06/2013	4	A	Information
Earth	11/06/2013	0.15	Ohm	Pass
Insulation	11/06/2013	>99.99	MOhm	Pass
Leakage	11/06/2013	<0.1	mA	Pass
Load	11/06/2013	<0.05	kVA	Information

Overall: Pass

Asset ID: 191	Description: TRICLOPS	User: USER 4	Test Instrument: Y42-0708	
Test Type	Date	Result	Unit	Status
Visual	11/06/2013			Pass
Earth Current	11/06/2013	4	A	Information
Earth	11/06/2013	0.12	Ohm	Pass
Insulation	11/06/2013	>99.99	MOhm	Pass
Leakage	11/06/2013	<0.1	mA	Pass
Load	11/06/2013	<0.05	kVA	Information

Overall: Pass

Asset ID: 192	Description: QTX FX	User: USER 4	Test Instrument: Y42-0708	
Test Type	Date	Result	Unit	Status
Visual	11/06/2013			Pass
Earth Current	11/06/2013	4	A	Information
Earth	11/06/2013	0.1	Ohm	Pass
Insulation	11/06/2013	>99.99	MOhm	Pass
Leakage	11/06/2013	<0.1	mA	Pass
Load	11/06/2013	<0.05	kVA	Information

Overall: Pass

Asset ID: 193	Description: QTX FX	User: USER 4	Test Instrument: Y42-0708	
Test Type	Date	Result	Unit	Status
Visual	11/06/2013			Pass
Earth Current	11/06/2013	4	A	Information
Earth	11/06/2013	0.07	Ohm	Pass
Insulation	11/06/2013	>99.99	MOhm	Pass
Leakage	11/06/2013	<0.1	mA	Pass
Load	11/06/2013	<0.05	kVA	Information

Overall: Pass

Asset ID: 194	Description: QTX FX	User: USER 4	Test Instrument: Y42-0708	
Test Type	Date	Result	Unit	Status
Visual	11/06/2013			Pass
Earth Current	11/06/2013	4	A	Information
Earth	11/06/2013	0.09	Ohm	Pass
Insulation	11/06/2013	>99.99	MOhm	Pass
Leakage	11/06/2013	<0.1	mA	Pass
Load	11/06/2013	<0.05	kVA	Information

Overall: Pass

Asset ID: 195	Description: QTX FX	User: USER 4	Test Instrument: Y42-0708	
Test Type	Date	Result	Unit	Status
Visual	11/06/2013			Pass
Earth Current	11/06/2013	4	A	Information
Earth	11/06/2013	0.06	Ohm	Pass
Insulation	11/06/2013	>99.99	MOhm	Pass
Leakage	11/06/2013	0.17	mA	Pass
Load	11/06/2013	<0.05	kVA	Information

Overall: Pass

Asset ID: 196	Description: QTX FX	User: USER 4	Test Instrument: Y42-0708	
Test Type	Date	Result	Unit	Status
Visual	11/06/2013			Pass
Earth Current	11/06/2013	4	A	Information
Earth	11/06/2013	0.09	Ohm	Pass
Insulation	11/06/2013	>99.99	MOhm	Pass
Leakage	11/06/2013	<0.1	mA	Pass
Load	11/06/2013	<0.05	kVA	Information

Overall: Pass

Detailed Test History



Test Status: All, Test Type: All
Person: All, Instrument: All
From: 11/06/2013 To: 10/06/2014

Asset ID: 197	Description: EXT	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Earth Current	11/06/2013	25	A Information
Earth	11/06/2013	0.33	Ohm Pass
Insulation	11/06/2013	>99.99	MOhm Pass
Polarity	11/06/2013		Pass

Overall: Pass

Asset ID: 198	Description: DYNAMO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Earth Current	11/06/2013	25	A Information
Earth	11/06/2013	0.05	Ohm Pass
Insulation	11/06/2013	>99.99	MOhm Pass
Leakage	11/06/2013	<0.1	mA Pass
Load	11/06/2013	<0.05	kVA Information

Overall: Pass

Asset ID: 199	Description: DYNAMO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Earth Current	11/06/2013	25	A Information
Earth	11/06/2013	0.06	Ohm Pass
Insulation	11/06/2013	>99.99	MOhm Pass
Leakage	11/06/2013	<0.1	mA Pass
Load	11/06/2013	<0.05	kVA Information

Overall: Pass

Asset ID: 200	Description: DYNAMO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Earth Current	11/06/2013	25	A Information
Earth	11/06/2013	0.06	Ohm Pass
Insulation	11/06/2013	>99.99	MOhm Pass
Leakage	11/06/2013	<0.1	mA Pass
Load	11/06/2013	<0.05	kVA Information

Overall: Pass

Asset ID: 201	Description: DYNAMO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Earth Current	11/06/2013	4	A Information
Earth	11/06/2013	0.09	Ohm Pass
Insulation	11/06/2013	>99.99	MOhm Pass
Leakage	11/06/2013	<0.1	mA Pass
Load	11/06/2013	<0.05	kVA Information

Overall: Pass

Asset ID: 202	Description: DYNAMO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Earth Current	11/06/2013	4	A Information
Earth	11/06/2013	0.04	Ohm Pass
Insulation	11/06/2013	>99.99	MOhm Pass
Leakage	11/06/2013	<0.1	mA Pass
Load	11/06/2013	<0.05	kVA Information

Overall: Pass

Asset ID: 203	Description: DYNAMO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass
Earth Current	11/06/2013	4	A Information
Earth	11/06/2013	0.04	Ohm Pass
Insulation	11/06/2013	>99.99	MOhm Pass
Leakage	11/06/2013	<0.1	mA Pass
Load	11/06/2013	<0.05	kVA Information

Overall: Pass

Asset ID: 204	Description: DYNAMO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	11/06/2013		Pass

Detailed Test History



Test Status: All, Test Type: All
Person: All, Instrument: All
From: 11/06/2013 To: 10/06/2014

Earth Current	11/06/2013	4	A	Information
Earth	11/06/2013	0.04	Ohm	Pass
Insulation	11/06/2013	>99.99	MOhm	Pass
Leakage	11/06/2013	<0.1	mA	Pass
Load	11/06/2013	<0.05	kVA	Information

Overall: Pass

Asset ID: 205 Description: DYNAMO User: USER 4 Test Instrument: Y42-0708

Test Type	Date	Result	Unit	Status
Visual	11/06/2013			Pass
Earth Current	11/06/2013	4	A	Information
Earth	11/06/2013	0.04	Ohm	Pass
Insulation	11/06/2013	>99.99	MOhm	Pass
Leakage	11/06/2013	<0.1	mA	Pass
Load	11/06/2013	<0.05	kVA	Information

Overall: Pass

Asset ID: 206 Description: DYNAMO User: USER 4 Test Instrument: Y42-0708

Test Type	Date	Result	Unit	Status
Visual	11/06/2013			Pass
Earth Current	11/06/2013	4	A	Information
Earth	11/06/2013	0.04	Ohm	Pass
Insulation	11/06/2013	>99.99	MOhm	Pass
Leakage	11/06/2013	<0.1	mA	Pass
Load	11/06/2013	<0.05	kVA	Information

Overall: Pass

Asset ID: 207 Description: DYNAMO User: USER 4 Test Instrument: Y42-0708

Test Type	Date	Result	Unit	Status
Visual	11/06/2013			Pass
Earth Current	11/06/2013	4	A	Information
Earth	11/06/2013	0.04	Ohm	Pass
Insulation	11/06/2013	>99.99	MOhm	Pass
Leakage	11/06/2013	<0.1	mA	Pass
Load	11/06/2013	<0.05	kVA	Information

Overall: Pass

Asset ID: 208 Description: DYNAMO User: USER 4 Test Instrument: Y42-0708

Test Type	Date	Result	Unit	Status
Visual	11/06/2013			Pass
Earth Current	11/06/2013	4	A	Information
Earth	11/06/2013	0.04	Ohm	Pass
Insulation	11/06/2013	>99.99	MOhm	Pass
Leakage	11/06/2013	<0.1	mA	Pass
Load	11/06/2013	<0.05	kVA	Information

Overall: Pass

Asset ID: 209 Description: DYNAMO User: USER 4 Test Instrument: Y42-0708

Test Type	Date	Result	Unit	Status
Visual	11/06/2013			Pass
Earth Current	11/06/2013	4	A	Information
Earth	11/06/2013	0.04	Ohm	Pass
Insulation	11/06/2013	>99.99	MOhm	Pass
Leakage	11/06/2013	<0.1	mA	Pass
Load	11/06/2013	<0.05	kVA	Information

Overall: Pass

Asset ID: 210 Description: SMOKE MACHINE User: USER 4 Test Instrument: Y42-0708

Test Type	Date	Result	Unit	Status
Visual	11/06/2013			Pass
Earth Current	11/06/2013	4	A	Information
Earth	11/06/2013	0.06	Ohm	Pass
Insulation	11/06/2013	9.17	MOhm	Pass
Leakage	11/06/2013	<0.1	mA	Pass
Load	11/06/2013	1	kVA	Information

Overall: Pass

Asset ID: 211 Description: SMOKE MACHINE User: USER 4 Test Instrument: Y42-0708

Test Type	Date	Result	Unit	Status
Visual	11/06/2013			Pass
Earth Current	11/06/2013	4	A	Information
Earth	11/06/2013	0.06	Ohm	Pass

Detailed Test History



Test Status: All, Test Type: All
Person: All, Instrument: All
From: 11/06/2013 To: 10/06/2014

Insulation	11/06/2013	11.07	MOhm	Pass
Leakage	11/06/2013	<0.1	mA	Pass
Load	11/06/2013	<0.05	kVA	Information

Overall: Pass

Asset ID: 242	Description: EXT	User: USER 4	Test Instrument: Y42-0708
---------------	------------------	--------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	13/06/2013			Pass
Earth Current	13/06/2013	25	A	Information
Earth	13/06/2013	0.11	Ohm	Pass
Insulation	13/06/2013	>99.99	MOhm	Pass
Polarity	13/06/2013			Pass

Overall: Pass

Asset ID: 243	Description: 243	User: USER 4	Test Instrument: Y42-0708
---------------	------------------	--------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	13/06/2013			Pass
Earth Current	13/06/2013	25	A	Information
Earth	13/06/2013	0.1	Ohm	Pass
Insulation	13/06/2013	>99.99	MOhm	Pass
Polarity	13/06/2013			Pass

Overall: Pass

Asset ID: 244	Description: POWER PACK	User: USER 4	Test Instrument: Y42-0708
---------------	-------------------------	--------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	13/06/2013			Pass
Earth Current	13/06/2013	25	A	Information
Earth	13/06/2013	0.12	Ohm	Pass
Insulation	13/06/2013	>99.99	MOhm	Pass
Polarity	13/06/2013			Pass

Overall: Pass

Asset ID: 245	Description: EXT	User: USER 4	Test Instrument: Y42-0708
---------------	------------------	--------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	13/06/2013			Pass
Earth Current	13/06/2013	25	A	Information
Earth	13/06/2013	0.08	Ohm	Pass
Insulation	13/06/2013	>99.99	MOhm	Pass
Polarity	13/06/2013			Pass

Overall: Pass

Asset ID: 246	Description: EXT	User: USER 4	Test Instrument: Y42-0708
---------------	------------------	--------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	13/06/2013			Pass
Earth Current	13/06/2013	25	A	Information
Earth	13/06/2013	0.08	Ohm	Pass
Insulation	13/06/2013	>99.99	MOhm	Pass
Polarity	13/06/2013			Pass

Overall: Pass

Asset ID: 247	Description: POWER PACK	User: USER 4	Test Instrument: Y42-0708
---------------	-------------------------	--------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	13/06/2013			Pass
Earth Current	13/06/2013	25	A	Information
Earth	13/06/2013	0.1	Ohm	Pass
Insulation	13/06/2013	>99.99	MOhm	Pass
Polarity	13/06/2013			Pass

Overall: Pass

Asset ID: 248	Description: EXT	User: USER 4	Test Instrument: Y42-0708
---------------	------------------	--------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	13/06/2013			Pass
Earth Current	13/06/2013	25	A	Information
Earth	13/06/2013	0.13	Ohm	Pass
Insulation	13/06/2013	>99.99	MOhm	Pass
Polarity	13/06/2013			Pass

Overall: Pass

Asset ID: 249	Description: EXT	User: USER 4	Test Instrument: Y42-0708
---------------	------------------	--------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	13/06/2013			Pass
Earth Current	13/06/2013	25	A	Information

Detailed Test History



Test Status: All, Test Type: All
Person: All, Instrument: All
From: 11/06/2013 To: 10/06/2014

Earth	13/06/2013	0.12	Ohm	Pass
Insulation	13/06/2013	>99.99	MOhm	Pass
Polarity	13/06/2013			Pass

Overall: Pass

Asset ID: 250	Description: EXT	User: USER 4	Test Instrument: Y42-0708
---------------	------------------	--------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	13/06/2013			Pass
Earth Current	13/06/2013	25	A	Information
Earth	13/06/2013	0.08	Ohm	Pass
Insulation	13/06/2013	>99.99	MOhm	Pass
Polarity	13/06/2013			Pass

Overall: Pass

Asset ID: 251	Description: EXT	User: USER 4	Test Instrument: Y42-0708
---------------	------------------	--------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	13/06/2013			Pass
Earth Current	13/06/2013	25	A	Information
Earth	13/06/2013	0.1	Ohm	Pass
Insulation	13/06/2013	>99.99	MOhm	Pass
Polarity	13/06/2013			Pass

Overall: Pass

Asset ID: 252	Description: EXT	User: USER 4	Test Instrument: Y42-0708
---------------	------------------	--------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	13/06/2013			Pass
Earth Current	13/06/2013	25	A	Information
Earth	13/06/2013	0.14	Ohm	Pass
Insulation	13/06/2013	>99.99	MOhm	Pass
Polarity	13/06/2013			Pass

Overall: Pass

Asset ID: 271	Description: EXT	User: USER 4	Test Instrument: Y42-0708
---------------	------------------	--------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	13/06/2013			Pass
Earth Current	13/06/2013	25	A	Information
Earth	13/06/2013	0.14	Ohm	Pass
Insulation	13/06/2013	>99.99	MOhm	Pass
Polarity	13/06/2013			Pass

Overall: Pass

Asset ID: 273	Description: EXT	User: USER 4	Test Instrument: Y42-0708
---------------	------------------	--------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	13/06/2013			Pass
Earth Current	13/06/2013	25	A	Information
Earth	13/06/2013	0.14	Ohm	Pass
Insulation	13/06/2013	>99.99	MOhm	Pass
Polarity	13/06/2013			Pass

Overall: Pass

Asset ID: 274	Description: EXT	User: USER 4	Test Instrument: Y42-0708
---------------	------------------	--------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	13/06/2013			Pass
Earth Current	13/06/2013	25	A	Information
Earth	13/06/2013	0.13	Ohm	Pass
Insulation	13/06/2013	>99.99	MOhm	Pass
Polarity	13/06/2013			Pass

Overall: Pass

Asset ID: 275	Description: EXT	User: USER 4	Test Instrument: Y42-0708
---------------	------------------	--------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	13/06/2013			Pass
Earth Current	13/06/2013	25	A	Information
Earth	13/06/2013	0.07	Ohm	Pass
Insulation	13/06/2013	>99.99	MOhm	Pass
Polarity	13/06/2013			Pass

Overall: Pass

Asset ID: 276	Description: EXT	User: USER 4	Test Instrument: Y42-0708
---------------	------------------	--------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	13/06/2013			Pass
Earth Current	13/06/2013	25	A	Information

Detailed Test History



Test Status: All, Test Type: All
Person: All, Instrument: All
From: 11/06/2013 To: 10/06/2014

Earth	13/06/2013	0.09	Ohm	Pass
Insulation	13/06/2013	>99.99	MOhm	Pass
Polarity	13/06/2013			Pass

Overall: Pass

Asset ID: 277	Description: POWER PACK	User: USER 4	Test Instrument: Y42-0708
---------------	-------------------------	--------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	13/06/2013			Pass
Earth Current	13/06/2013	25	A	Information
Earth	13/06/2013	0.09	Ohm	Pass
Insulation	13/06/2013	>99.99	MOhm	Pass
Polarity	13/06/2013			Pass

Overall: Pass

Asset ID: 293	Description: POWER PACK	User: USER 4	Test Instrument: Y42-0708
---------------	-------------------------	--------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	13/06/2013			Pass
Earth Current	13/06/2013	25	A	Information
Earth	13/06/2013	0.08	Ohm	Pass
Insulation	13/06/2013	>99.99	MOhm	Pass
Polarity	13/06/2013			Pass

Overall: Pass

Asset ID: 294	Description: EURO	User: USER 4	Test Instrument: Y42-0708
---------------	-------------------	--------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	13/06/2013			Pass
Earth Current	13/06/2013	25	A	Information
Earth	13/06/2013	0.04	Ohm	Pass
Insulation	13/06/2013	>99.99	MOhm	Pass
Polarity	13/06/2013			Pass

Overall: Pass

Asset ID: 295	Description: EXT	User: USER 4	Test Instrument: Y42-0708
---------------	------------------	--------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	13/06/2013			Pass
Earth Current	13/06/2013	25	A	Information
Earth	13/06/2013	0.12	Ohm	Pass
Insulation	13/06/2013	>99.99	MOhm	Pass
Polarity	13/06/2013			Pass

Overall: Pass

Asset ID: 296	Description: EXT	User: USER 4	Test Instrument: Y42-0708
---------------	------------------	--------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	13/06/2013			Pass
Earth Current	13/06/2013	25	A	Information
Earth	13/06/2013	0.09	Ohm	Pass
Insulation	13/06/2013	>99.99	MOhm	Pass
Polarity	13/06/2013			Pass

Overall: Pass

Asset ID: 297	Description: EXT	User: USER 4	Test Instrument: Y42-0708
---------------	------------------	--------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	13/06/2013			Pass
Earth Current	13/06/2013	25	A	Information
Earth	13/06/2013	0.14	Ohm	Pass
Insulation	13/06/2013	>99.99	MOhm	Pass
Polarity	13/06/2013			Pass

Overall: Pass

Asset ID: 298	Description: EXT	User: USER 4	Test Instrument: Y42-0708
---------------	------------------	--------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	13/06/2013			Pass
Earth Current	13/06/2013	25	A	Information
Earth	13/06/2013	0.09	Ohm	Pass
Insulation	13/06/2013	>99.99	MOhm	Pass
Polarity	13/06/2013			Pass

Overall: Pass

Asset ID: 299	Description: EXT	User: USER 4	Test Instrument: Y42-0708
---------------	------------------	--------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	13/06/2013			Pass
Earth Current	13/06/2013	25	A	Information

Detailed Test History



Test Status: All, Test Type: All
Person: All, Instrument: All
From: 11/06/2013 To: 10/06/2014

Earth	13/06/2013	0.09	Ohm	Pass
Insulation	13/06/2013	>99.99	MOhm	Pass
Polarity	13/06/2013			Pass

Overall: Pass

Asset ID: 300	Description: EXT	User: USER 4	Test Instrument: Y42-0708
---------------	------------------	--------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	13/06/2013			Pass
Earth Current	13/06/2013	25	A	Information
Earth	13/06/2013	0.04	Ohm	Pass
Insulation	13/06/2013	>99.99	MOhm	Pass
Polarity	13/06/2013			Pass

Overall: Pass

Asset ID: 301	Description: TRICLOPS	User: USER 4	Test Instrument: Y42-0708
---------------	-----------------------	--------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	13/06/2013			Pass
Earth Current	13/06/2013	25	A	Information
Earth	13/06/2013	0.04	Ohm	Pass
Insulation	13/06/2013	>99.99	MOhm	Pass
Polarity	13/06/2013			Pass

Overall: Pass

Asset ID: 302	Description: DYNAROCK	User: USER 4	Test Instrument: Y42-0708
---------------	-----------------------	--------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	13/06/2013			Pass
Earth Current	13/06/2013	4	A	Information
Earth	13/06/2013	0.04	Ohm	Pass
Insulation	13/06/2013	>99.99	MOhm	Pass
Leakage	13/06/2013	<0.1	mA	Pass
Load	13/06/2013	<0.05	kVA	Information

Overall: Pass

Asset ID: 303	Description: DYNAROCK	User: USER 4	Test Instrument: Y42-0708
---------------	-----------------------	--------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	13/06/2013			Pass
Earth Current	13/06/2013	4	A	Information
Earth	13/06/2013	0.06	Ohm	Pass
Insulation	13/06/2013	>99.99	MOhm	Pass
Leakage	13/06/2013	<0.1	mA	Pass
Load	13/06/2013	<0.05	kVA	Information

Overall: Pass

Asset ID: 304	Description: DYNAROCK	User: USER 4	Test Instrument: Y42-0708
---------------	-----------------------	--------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	13/06/2013			Pass
Earth Current	13/06/2013	4	A	Information
Earth	13/06/2013	0.05	Ohm	Pass
Insulation	13/06/2013	>99.99	MOhm	Pass
Leakage	13/06/2013	<0.1	mA	Pass
Load	13/06/2013	<0.05	kVA	Information

Overall: Pass

Asset ID: 305	Description: DYNAROCK	User: USER 4	Test Instrument: Y42-0708
---------------	-----------------------	--------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	13/06/2013			Pass
Earth Current	13/06/2013	4	A	Information
Earth	13/06/2013	0.04	Ohm	Pass
Insulation	13/06/2013	>99.99	MOhm	Pass
Leakage	13/06/2013	<0.1	mA	Pass
Load	13/06/2013	<0.05	kVA	Information

Overall: Pass

Asset ID: 306	Description: DYNAROCK	User: USER 4	Test Instrument: Y42-0708
---------------	-----------------------	--------------	---------------------------

Test Type	Date	Result	Unit	Status
Visual	13/06/2013			Pass
Earth Current	13/06/2013	4	A	Information
Earth	13/06/2013	0.04	Ohm	Pass
Insulation	13/06/2013	>99.99	MOhm	Pass
Leakage	13/06/2013	<0.1	mA	Pass
Load	13/06/2013	<0.05	kVA	Information

Detailed Test History



Test Status: All, Test Type: All
Person: All, Instrument: All
From: 11/06/2013 To: 10/06/2014

Overall: Pass

Asset ID: 307	Description: DYNAROCK	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	13/06/2013		Pass
Earth Current	13/06/2013	4	A Information
Earth	13/06/2013	0.06	Ohm Pass
Insulation	13/06/2013	>99.99	MOhm Pass
Leakage	13/06/2013	<0.1	mA Pass
Load	13/06/2013	<0.05	kVA Information

Overall: Pass

Asset ID: 308	Description: DYNAROCK	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	13/06/2013		Pass
Earth Current	13/06/2013	4	A Information
Earth	13/06/2013	0.04	Ohm Pass
Insulation	13/06/2013	>99.99	MOhm Pass
Leakage	13/06/2013	<0.1	mA Pass
Load	13/06/2013	<0.05	kVA Information

Overall: Pass

Asset ID: 309	Description: DYNAROCK	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	13/06/2013		Pass
Earth Current	13/06/2013	4	A Information
Earth	13/06/2013	0.05	Ohm Pass
Insulation	13/06/2013	>99.99	MOhm Pass
Leakage	13/06/2013	<0.1	mA Pass
Load	13/06/2013	<0.05	kVA Information

Overall: Pass

Asset ID: 310	Description: MIXER	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	13/06/2013		Pass
Earth Current	13/06/2013	4	A Information
Earth	13/06/2013	0.04	Ohm Pass
Insulation	13/06/2013	>99.99	MOhm Pass
Leakage	13/06/2013	<0.1	mA Pass
Load	13/06/2013	<0.05	kVA Information

Overall: Pass

Asset ID: 311	Description: CD PLAYER	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	13/06/2013		Pass
Insulation	13/06/2013	>99.99	MOhm Pass
Touch Leakage	13/06/2013	<0.1	mA Pass

Overall: Pass

Asset ID: 312	Description: LIGHT CONTROLER	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	13/06/2013		Pass
Earth Current	13/06/2013	4	A Information
Earth	13/06/2013	0.04	Ohm Pass
Insulation	13/06/2013	>99.99	MOhm Pass
Leakage	13/06/2013	<0.1	mA Pass
Load	13/06/2013	<0.05	kVA Information

Overall: Pass

Asset ID: 313	Description: LIGHT CONTROLER	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	13/06/2013		Pass
Earth Current	13/06/2013	4	A Information
Earth	13/06/2013	0.04	Ohm Pass
Insulation	13/06/2013	>99.99	MOhm Pass
Leakage	13/06/2013	<0.1	mA Pass
Load	13/06/2013	<0.05	kVA Information

Overall: Pass

Asset ID: 314	Description: AMP	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	13/06/2013		Pass

Detailed Test History



Test Status: All, Test Type: All
Person: All, Instrument: All
From: 11/06/2013 To: 10/06/2014

Earth Current	13/06/2013	4	A	Information
Earth	13/06/2013	0.08	Ohm	Pass
Insulation	13/06/2013	>99.99	MOhm	Pass
Leakage	13/06/2013	0.33	mA	Pass
Load	13/06/2013	<0.05	kVA	Information

Overall: Pass

Asset ID: 315 Description: AMP User: USER 4 Test Instrument: Y42-0708

Test Type	Date	Result	Unit	Status
Visual	13/06/2013			Pass
Earth Current	13/06/2013	4	A	Information
Earth	13/06/2013	0.06	Ohm	Pass
Insulation	13/06/2013	>99.99	MOhm	Pass
Leakage	13/06/2013	<0.1	mA	Pass
Load	13/06/2013	<0.05	kVA	Information

Overall: Pass

Asset ID: 316 Description: BUBBLE MACHINE User: USER 4 Test Instrument: Y42-0708

Test Type	Date	Result	Unit	Status
Visual	13/06/2013			Pass
Earth Current	13/06/2013	4	A	Information
Earth	13/06/2013	0.1	Ohm	Pass
Insulation	13/06/2013	>99.99	MOhm	Pass
Leakage	13/06/2013	<0.1	mA	Pass
Load	13/06/2013	0.1	kVA	Information

Overall: Pass

Asset ID: 317 Description: BUBBLE MACHINE User: USER 4 Test Instrument: Y42-0708

Test Type	Date	Result	Unit	Status
Visual	13/06/2013			Pass
Earth Current	13/06/2013	4	A	Information
Earth	13/06/2013	0.04	Ohm	Pass
Insulation	13/06/2013	>99.99	MOhm	Pass
Leakage	13/06/2013	<0.1	mA	Pass
Load	13/06/2013	<0.05	kVA	Information

Overall: Pass

Client: DiscoCo.com Site: 70 CANTERBURY R Location: DURHAM

Asset ID: 150 Description: EURO User: Test Instrument: Y42-0708

Test Type	Date	Result	Unit	Status
Visual	12/06/2013			Pass
Earth Current	12/06/2013	25	A	Information
Earth	12/06/2013	0.04	OHM	Pass
Insulation	12/06/2013	>99.99	MEG	Pass
Polarity	12/06/2013			Pass

Overall: Pass

Asset ID: 151 Description: IEC User: Test Instrument: Y42-0708

Test Type	Date	Result	Unit	Status
Visual	12/06/2013			Pass
Earth Current	12/06/2013	25	A	Information
Earth	12/06/2013	0.04	OHM	Pass
Insulation	12/06/2013	>99.99	MEG	Pass
Polarity	12/06/2013			Pass

Overall: Pass

Asset ID: 152 Description: IEC User: Test Instrument: Y42-0708

Test Type	Date	Result	Unit	Status
Visual	12/06/2013			Pass
Earth Current	12/06/2013	25	A	Information
Earth	12/06/2013	0.04	OHM	Pass
Insulation	12/06/2013	>99.99	MEG	Pass
Polarity	12/06/2013			Pass

Overall: Pass

Asset ID: 153 Description: IEC User: Test Instrument: Y42-0708

Test Type	Date	Result	Unit	Status
Visual	12/06/2013			Pass
Earth Current	12/06/2013	25	A	Information
Earth	12/06/2013	0.04	OHM	Pass
Insulation	12/06/2013	>99.99	MEG	Pass
Polarity	12/06/2013			Pass

Detailed Test History



Test Status: All, Test Type: All
Person: All, Instrument: All
From: 11/06/2013 To: 10/06/2014

Overall: Pass

Asset ID: 154	Description: EURO	User:	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	OHM Pass
Insulation	12/06/2013	>99.99	MEG Pass
Polarity	12/06/2013		Pass

Overall: Pass

Asset ID: 155	Description: EURO	User:	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	OHM Pass
Insulation	12/06/2013	>99.99	MEG Pass
Polarity	12/06/2013		Pass

Overall: Pass

Asset ID: 156	Description: IEC	User:	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	OHM Pass
Insulation	12/06/2013	>99.99	MEG Pass
Polarity	12/06/2013		Pass

Overall: Pass

Asset ID: 157	Description: EURO	User:	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	OHM Pass
Insulation	12/06/2013	>99.99	MEG Pass
Polarity	12/06/2013		Pass

Overall: Pass

Asset ID: 158	Description: EURO	User:	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	OHM Pass
Insulation	12/06/2013	>99.99	MEG Pass
Polarity	12/06/2013		Pass

Overall: Pass

Asset ID: 159	Description: EURO	User:	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	OHM Pass
Insulation	12/06/2013	>99.99	MEG Pass
Polarity	12/06/2013		Pass

Overall: Pass

Asset ID: 160	Description: EURO	User:	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	OHM Pass
Insulation	12/06/2013	>99.99	MEG Pass
Polarity	12/06/2013		Pass

Overall: Pass

Asset ID: 161	Description: IEC	User:	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	A Information
Earth	12/06/2013	0.04	OHM Pass
Insulation	12/06/2013	>99.99	MEG Pass
Polarity	12/06/2013		Pass

Detailed Test History



Test Status: All, Test Type: All
Person: All, Instrument: All
From: 11/06/2013 To: 10/06/2014

Overall: Pass

Asset ID: 223		Description: IEC		User:		Test Instrument: Y42-0708	
Test Type	Date	Result	Unit	Status			
Visual	12/06/2013			Pass			
Earth Current	12/06/2013	25	A	Information			
Earth	12/06/2013	0.04	OHM	Pass			
Insulation	12/06/2013	>99.99	MEG	Pass			
Polarity	12/06/2013			Pass			
Visual	12/06/2013			Pass			
Earth Current	12/06/2013	25	A	Information			
Earth	12/06/2013	0.04	OHM	Pass			
Insulation	12/06/2013	>99.99	MEG	Pass			
Polarity	12/06/2013			Pass			

Overall: Pass

Asset ID: 224		Description: IEC		User:		Test Instrument: Y42-0708	
Test Type	Date	Result	Unit	Status			
Visual	12/06/2013			Pass			
Earth Current	12/06/2013	25	A	Information			
Earth	12/06/2013	0.04	OHM	Pass			
Insulation	12/06/2013	>99.99	MEG	Pass			
Polarity	12/06/2013			Pass			

Overall: Pass

Asset ID: 225		Description: IEC		User:		Test Instrument: Y42-0708	
Test Type	Date	Result	Unit	Status			
Visual	12/06/2013			Pass			
Earth Current	12/06/2013	25	A	Information			
Earth	12/06/2013	0.04	OHM	Pass			
Insulation	12/06/2013	>99.99	MEG	Pass			
Polarity	12/06/2013			Pass			

Overall: Pass

Asset ID: 226		Description: IEC		User:		Test Instrument: Y42-0708	
Test Type	Date	Result	Unit	Status			
Visual	12/06/2013			Pass			
Earth Current	12/06/2013	25	A	Information			
Earth	12/06/2013	0.04	OHM	Pass			
Insulation	12/06/2013	>99.99	MEG	Pass			
Polarity	12/06/2013			Pass			

Overall: Pass

Asset ID: 227		Description: IEC		User:		Test Instrument: Y42-0708	
Test Type	Date	Result	Unit	Status			
Visual	12/06/2013			Pass			
Earth Current	12/06/2013	25	A	Information			
Earth	12/06/2013	0.04	OHM	Pass			
Insulation	12/06/2013	>99.99	MEG	Pass			
Polarity	12/06/2013			Pass			

Overall: Pass

Asset ID: 228		Description: IEC		User:		Test Instrument: Y42-0708	
Test Type	Date	Result	Unit	Status			
Visual	12/06/2013			Pass			
Earth Current	12/06/2013	25	A	Information			
Earth	12/06/2013	0.04	OHM	Pass			
Insulation	12/06/2013	>99.99	MEG	Pass			
Polarity	12/06/2013			Pass			

Overall: Pass

Asset ID: 229		Description: IEC		User:		Test Instrument: Y42-0708	
Test Type	Date	Result	Unit	Status			
Visual	12/06/2013			Pass			
Earth Current	12/06/2013	25	A	Information			
Earth	12/06/2013	0.04	OHM	Pass			
Insulation	12/06/2013	>99.99	MEG	Pass			
Polarity	12/06/2013			Pass			

Overall: Pass

Detailed Test History



Test Status: All, Test Type: All
Person: All, Instrument: All
From: 11/06/2013 To: 10/06/2014

Asset ID: 230	Description: IEC	User:	Test Instrument: Y42-0708
Test Type	Date	Result	Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	Information
Earth	12/06/2013	0.04	Pass
Insulation	12/06/2013	>99.99	Pass
Polarity	12/06/2013		Pass

Overall: Pass

Asset ID: 231	Description: IEC	User:	Test Instrument: Y42-0708
Test Type	Date	Result	Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	Information
Earth	12/06/2013	0.04	Pass
Insulation	12/06/2013	>99.99	Pass
Leakage	12/06/2013	<0.10	Pass
Load	12/06/2013	<0.05	Pass

Overall: Pass

Asset ID: 232	Description: IEC	User:	Test Instrument: Y42-0708
Test Type	Date	Result	Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	Information
Earth	12/06/2013	0.04	Pass
Insulation	12/06/2013	>99.99	Pass
Polarity	12/06/2013		Pass

Overall: Pass

Asset ID: 233	Description: IEC	User:	Test Instrument: Y42-0708
Test Type	Date	Result	Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	Information
Earth	12/06/2013	0.04	Pass
Insulation	12/06/2013	>99.99	Pass
Polarity	12/06/2013		Pass

Overall: Pass

Asset ID: 234	Description: IEC	User:	Test Instrument: Y42-0708
Test Type	Date	Result	Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	Information
Earth	12/06/2013	0.04	Pass
Insulation	12/06/2013	>99.99	Pass
Polarity	12/06/2013		Pass

Overall: Pass

Asset ID: 235	Description: IEC	User:	Test Instrument: Y42-0708
Test Type	Date	Result	Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	Information
Earth	12/06/2013	0.04	Pass
Insulation	12/06/2013	>99.99	Pass
Polarity	12/06/2013		Pass

Overall: Pass

Asset ID: 236	Description: EURO	User:	Test Instrument: Y42-0708
Test Type	Date	Result	Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	Information
Earth	12/06/2013	0.04	Pass
Insulation	12/06/2013	>99.99	Pass
Polarity	12/06/2013		Pass

Overall: Pass

Asset ID: 237	Description: EURO	User:	Test Instrument: Y42-0708
Test Type	Date	Result	Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	Information
Earth	12/06/2013	0.04	Pass
Insulation	12/06/2013	>99.99	Pass
Polarity	12/06/2013		Pass

Detailed Test History



Test Status: All, Test Type: All
Person: All, Instrument: All
From: 11/06/2013 To: 10/06/2014

Overall: Pass

Asset ID: 238	Description: EURO	User:	Test Instrument: Y42-0708
Test Type	Date	Result	Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	Information
Earth	12/06/2013	0.04	Pass
Insulation	12/06/2013	>99.99	Pass
Polarity	12/06/2013		Pass

Overall: Pass

Asset ID: 239	Description: EURO	User:	Test Instrument: Y42-0708
Test Type	Date	Result	Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	Information
Earth	12/06/2013	0.04	Pass
Insulation	12/06/2013	>99.99	Pass
Polarity	12/06/2013		Pass

Overall: Pass

Asset ID: 240	Description: EURO	User:	Test Instrument: Y42-0708
Test Type	Date	Result	Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	Information
Earth	12/06/2013	0.04	Pass
Insulation	12/06/2013	>99.99	Pass
Polarity	12/06/2013		Pass

Overall: Pass

Asset ID: 241	Description: EURO	User:	Test Instrument: Y42-0708
Test Type	Date	Result	Status
Visual	12/06/2013		Pass
Earth Current	12/06/2013	25	Information
Earth	12/06/2013	0.04	Pass
Insulation	12/06/2013	>99.99	Pass
Polarity	12/06/2013		Pass

Overall: Pass

Client: DiscoCo.com	Site: CANTERBURY	Location: DURHAM	
Asset ID: 025	Description: TRICLOPS	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Status
Visual	15/06/2013		Pass
Earth Current	15/06/2013	4	Information
Earth	15/06/2013	0.05	Pass
Insulation	15/06/2013	>99.99	Pass
Leakage	15/06/2013	<0.1	Pass
Load	15/06/2013	<0.05	Information

Overall: Pass

Asset ID: 026	Description: TRICLOPS	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Status
Visual	15/06/2013		Pass
Earth Current	15/06/2013	4	Information
Earth	15/06/2013	0.05	Pass
Insulation	15/06/2013	>99.99	Pass
Leakage	15/06/2013	<0.1	Pass
Load	15/06/2013	<0.05	Information

Overall: Pass

Asset ID: 027	Description: TRICLOPS	User: USER 4	Test Instrument: Y42-0708
Comments: TRICLOPS			
Test Type	Date	Result	Status
Visual	15/06/2013		Pass
Earth Current	15/06/2013	4	Information
Earth	15/06/2013	0.05	Pass
Insulation	15/06/2013	>99.99	Pass
Leakage	15/06/2013	<0.1	Pass
Load	15/06/2013	<0.05	Information

Overall: Pass

Detailed Test History



Test Status: All, Test Type: All
Person: All, Instrument: All
From: 11/06/2013 To: 10/06/2014

Asset ID: 028	Description: TRICLOPS	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	15/06/2013		Pass
Earth Current	15/06/2013	4	A Information
Earth	15/06/2013	0.05	Ohm Pass
Insulation	15/06/2013	>99.99	MOhm Pass
Leakage	15/06/2013	<0.1	mA Pass
Load	15/06/2013	<0.05	kVA Information
Overall: Pass			

Asset ID: 029	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	15/06/2013		Pass
Earth Current	15/06/2013	4	A Information
Earth	15/06/2013	0.05	Ohm Pass
Insulation	15/06/2013	>99.99	MOhm Pass
Leakage	15/06/2013	<0.1	mA Pass
Load	15/06/2013	<0.05	kVA Information
Overall: Pass			

Asset ID: 030	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	15/06/2013		Pass
Earth Current	15/06/2013	25	A Information
Earth	15/06/2013	0.05	Ohm Pass
Insulation	15/06/2013	>99.99	MOhm Pass
Polarity	15/06/2013		Pass
Overall: Pass			

Asset ID: 031	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	15/06/2013		Pass
Earth Current	15/06/2013	25	A Information
Earth	15/06/2013	0.04	Ohm Pass
Insulation	15/06/2013	>99.99	MOhm Pass
Polarity	15/06/2013		Pass
Overall: Pass			

Asset ID: 032	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	15/06/2013		Pass
Earth Current	15/06/2013	25	A Information
Earth	15/06/2013	0.04	Ohm Pass
Insulation	15/06/2013	>99.99	MOhm Pass
Polarity	15/06/2013		Pass
Overall: Pass			

Asset ID: 033	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	15/06/2013		Pass
Earth Current	15/06/2013	25	A Information
Earth	15/06/2013	0.04	Ohm Pass
Insulation	15/06/2013	>99.99	MOhm Pass
Polarity	15/06/2013		Pass
Overall: Pass			

Asset ID: 034	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	15/06/2013		Pass
Earth Current	15/06/2013	25	A Information
Earth	15/06/2013	0.04	Ohm Pass
Insulation	15/06/2013	>99.99	MOhm Pass
Polarity	15/06/2013		Pass
Overall: Pass			

Asset ID: 035	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	15/06/2013		Pass
Earth Current	15/06/2013	25	A Information
Earth	15/06/2013	0.04	Ohm Pass
Insulation	15/06/2013	>99.99	MOhm Pass
Polarity	15/06/2013		Pass

Detailed Test History



Test Status: All, Test Type: All
Person: All, Instrument: All
From: 11/06/2013 To: 10/06/2014

Overall: Pass

Asset ID: 036	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	15/06/2013		Pass
Earth Current	15/06/2013	25	A Information
Earth	15/06/2013	0.04	Ohm Pass
Insulation	15/06/2013	>99.99	MOhm Pass
Polarity	15/06/2013		Pass

Overall: Pass

Asset ID: 037	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	15/06/2013		Pass
Earth Current	15/06/2013	25	A Information
Earth	15/06/2013	0.04	Ohm Pass
Insulation	15/06/2013	>99.99	MOhm Pass
Polarity	15/06/2013		Pass

Overall: Pass

Asset ID: 038	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	15/06/2013		Pass
Earth Current	15/06/2013	25	A Information
Earth	15/06/2013	0.04	Ohm Pass
Insulation	15/06/2013	>99.99	MOhm Pass
Polarity	15/06/2013		Pass

Overall: Pass

Asset ID: 039	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	15/06/2013		Pass
Earth Current	15/06/2013	25	A Information
Earth	15/06/2013	0.04	Ohm Pass
Insulation	15/06/2013	>99.99	MOhm Pass
Polarity	15/06/2013		Pass

Overall: Pass

Asset ID: 040	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	15/06/2013		Pass
Earth Current	15/06/2013	25	A Information
Earth	15/06/2013	0.04	Ohm Pass
Insulation	15/06/2013	>99.99	MOhm Pass
Polarity	15/06/2013		Pass

Overall: Pass

Asset ID: 041	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	15/06/2013		Pass
Earth Current	15/06/2013	25	A Information
Earth	15/06/2013	0.04	Ohm Pass
Insulation	15/06/2013	>99.99	MOhm Pass
Polarity	15/06/2013		Pass

Overall: Pass

Asset ID: 045	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	15/06/2013		Pass
Earth Current	15/06/2013	25	A Information
Earth	15/06/2013	0.04	Ohm Pass
Insulation	15/06/2013	>99.99	MOhm Pass
Polarity	15/06/2013		Pass

Overall: Pass

Asset ID: 046	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	15/06/2013		Pass
Earth Current	15/06/2013	25	A Information
Earth	15/06/2013	0.04	Ohm Pass
Insulation	15/06/2013	>99.99	MOhm Pass
Polarity	15/06/2013		Pass

Detailed Test History



Test Status: All, Test Type: All
Person: All, Instrument: All
From: 11/06/2013 To: 10/06/2014

Overall: Pass

Asset ID: 047	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Status
Visual	15/06/2013		Pass
Earth Current	15/06/2013	25	Information
Earth	15/06/2013	0.04	Pass
Insulation	15/06/2013	>99.99	Pass
Polarity	15/06/2013		Pass

Overall: Pass

Asset ID: 048	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Status
Visual	15/06/2013		Pass
Earth Current	15/06/2013	25	Information
Earth	15/06/2013	0.04	Pass
Insulation	15/06/2013	>99.99	Pass
Polarity	15/06/2013		Pass

Overall: Pass

Asset ID: 049	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Status
Visual	15/06/2013		Pass
Earth Current	15/06/2013	25	Information
Earth	15/06/2013	0.04	Pass
Insulation	15/06/2013	>99.99	Pass
Polarity	15/06/2013		Pass

Overall: Pass

Asset ID: 050	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Status
Visual	15/06/2013		Pass
Earth Current	15/06/2013	25	Information
Earth	15/06/2013	0.04	Pass
Insulation	15/06/2013	>99.99	Pass
Polarity	15/06/2013		Pass

Overall: Pass

Asset ID: 051	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Status
Visual	15/06/2013		Pass
Earth Current	15/06/2013	25	Information
Earth	15/06/2013	0.04	Pass
Insulation	15/06/2013	>99.99	Pass
Polarity	15/06/2013		Pass

Overall: Pass

Asset ID: 052	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Status
Visual	15/06/2013		Pass
Earth Current	15/06/2013	25	Information
Earth	15/06/2013	0.04	Pass
Insulation	15/06/2013	>99.99	Pass
Polarity	15/06/2013		Pass

Overall: Pass

Asset ID: 053	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Status
Visual	15/06/2013		Pass
Earth Current	15/06/2013	25	Information
Earth	15/06/2013	0.04	Pass
Insulation	15/06/2013	>99.99	Pass
Polarity	15/06/2013		Pass

Overall: Pass

Asset ID: 054	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Status
Visual	15/06/2013		Pass
Earth Current	15/06/2013	25	Information
Earth	15/06/2013	0.04	Pass
Insulation	15/06/2013	>99.99	Pass
Polarity	15/06/2013		Pass

Detailed Test History



Test Status: All, Test Type: All
Person: All, Instrument: All
From: 11/06/2013 To: 10/06/2014

Overall: Pass

Asset ID: 055	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	15/06/2013		Pass
Earth Current	15/06/2013	25	A Information
Earth	15/06/2013	0.04	Ohm Pass
Insulation	15/06/2013	>99.99	MOhm Pass
Polarity	15/06/2013		Pass

Overall: Pass

Asset ID: 056	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	15/06/2013		Pass
Earth Current	15/06/2013	25	A Information
Earth	15/06/2013	0.04	Ohm Pass
Insulation	15/06/2013	>99.99	MOhm Pass
Polarity	15/06/2013		Pass

Overall: Pass

Asset ID: 057	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	15/06/2013		Pass
Earth Current	15/06/2013	25	A Information
Earth	15/06/2013	0.04	Ohm Pass
Insulation	15/06/2013	>99.99	MOhm Pass
Polarity	15/06/2013		Pass

Overall: Pass

Asset ID: 058	Description: IEC	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	15/06/2013		Pass
Earth Current	15/06/2013	25	A Information
Earth	15/06/2013	0.04	Ohm Pass
Insulation	15/06/2013	>99.99	MOhm Pass
Polarity	15/06/2013		Pass

Overall: Pass

Asset ID: 059	Description: IEC	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	15/06/2013		Pass
Earth Current	15/06/2013	25	A Information
Earth	15/06/2013	0.04	Ohm Pass
Insulation	15/06/2013	>99.99	MOhm Pass
Polarity	15/06/2013		Pass

Overall: Pass

Asset ID: 067	Description: IEC	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	15/06/2013		Pass
Earth Current	15/06/2013	25	A Information
Earth	15/06/2013	0.04	Ohm Pass
Insulation	15/06/2013	>99.99	MOhm Pass
Polarity	15/06/2013		Pass

Overall: Pass

Asset ID: 068	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	17/06/2013		Pass
Earth Current	17/06/2013	25	A Information
Earth	17/06/2013	0.04	Ohm Pass
Insulation	17/06/2013	>99.99	MOhm Pass
Polarity	17/06/2013		Pass

Overall: Pass

Asset ID: 069	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	17/06/2013		Pass
Earth Current	17/06/2013	25	A Information
Earth	17/06/2013	0.04	Ohm Pass
Insulation	17/06/2013	>99.99	MOhm Pass
Polarity	17/06/2013		Pass

Detailed Test History



Test Status: All, Test Type: All
Person: All, Instrument: All
From: 11/06/2013 To: 10/06/2014

Overall: Pass

Asset ID: 212	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	17/06/2013		Pass
Earth Current	17/06/2013	25	A Information
Earth	17/06/2013	0.04	Ohm Pass
Insulation	17/06/2013	>99.99	MOhm Pass
Polarity	17/06/2013		Pass

Overall: Pass

Asset ID: 213	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	17/06/2013		Pass
Earth Current	17/06/2013	25	A Information
Earth	17/06/2013	0.04	Ohm Pass
Insulation	17/06/2013	>99.99	MOhm Pass
Polarity	17/06/2013		Pass

Overall: Pass

Asset ID: 214	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	17/06/2013		Pass
Earth Current	17/06/2013	25	A Information
Earth	17/06/2013	0.04	Ohm Pass
Insulation	17/06/2013	>99.99	MOhm Pass
Polarity	17/06/2013		Pass

Overall: Pass

Asset ID: 215	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	17/06/2013		Pass
Earth Current	17/06/2013	25	A Information
Earth	17/06/2013	0.04	Ohm Pass
Insulation	17/06/2013	>99.99	MOhm Pass
Polarity	17/06/2013		Pass

Overall: Pass

Asset ID: 216	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	17/06/2013		Pass
Earth Current	17/06/2013	25	A Information
Earth	17/06/2013	0.04	Ohm Pass
Insulation	17/06/2013	>99.99	MOhm Pass
Polarity	17/06/2013		Pass

Overall: Pass

Asset ID: 217	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	17/06/2013		Pass
Earth Current	17/06/2013	25	A Information
Earth	17/06/2013	0.04	Ohm Pass
Insulation	17/06/2013	>99.99	MOhm Pass
Polarity	17/06/2013		Pass

Overall: Pass

Asset ID: 218	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	17/06/2013		Pass
Earth Current	17/06/2013	25	A Information
Earth	17/06/2013	0.04	Ohm Pass
Insulation	17/06/2013	>99.99	MOhm Pass
Polarity	17/06/2013		Pass

Overall: Pass

Asset ID: 219	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	17/06/2013		Pass
Earth Current	17/06/2013	25	A Information
Earth	17/06/2013	0.04	Ohm Pass
Insulation	17/06/2013	>99.99	MOhm Pass
Polarity	17/06/2013		Pass

Detailed Test History



Test Status: All, Test Type: All
Person: All, Instrument: All
From: 11/06/2013 To: 10/06/2014

Overall: Pass

Asset ID: 220	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	17/06/2013		Pass
Earth Current	17/06/2013	25	A Information
Earth	17/06/2013	0.04	Ohm Pass
Insulation	17/06/2013	>99.99	MOhm Pass
Polarity	17/06/2013		Pass

Overall: Pass

Asset ID: 221	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	17/06/2013		Pass
Earth Current	17/06/2013	25	A Information
Earth	17/06/2013	0.04	Ohm Pass
Insulation	17/06/2013	>99.99	MOhm Pass
Polarity	17/06/2013		Pass

Overall: Pass

Asset ID: 222	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	17/06/2013		Pass
Earth Current	17/06/2013	25	A Information
Earth	17/06/2013	0.04	Ohm Pass
Insulation	17/06/2013	>99.99	MOhm Pass
Polarity	17/06/2013		Pass

Overall: Pass

Asset ID: 253	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	17/06/2013		Pass
Earth Current	17/06/2013	25	A Information
Earth	17/06/2013	0.04	Ohm Pass
Insulation	17/06/2013	>99.99	MOhm Pass
Polarity	17/06/2013		Pass

Overall: Pass

Asset ID: 254	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	17/06/2013		Pass
Earth Current	17/06/2013	25	A Information
Earth	17/06/2013	0.04	Ohm Pass
Insulation	17/06/2013	>99.99	MOhm Pass
Polarity	17/06/2013		Pass

Overall: Pass

Asset ID: 255	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	17/06/2013		Pass
Earth Current	17/06/2013	25	A Information
Earth	17/06/2013	0.04	Ohm Pass
Insulation	17/06/2013	>99.99	MOhm Pass
Polarity	17/06/2013		Pass

Overall: Pass

Asset ID: 256	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	17/06/2013		Pass
Earth Current	17/06/2013	25	A Information
Earth	17/06/2013	0.04	Ohm Pass
Insulation	17/06/2013	>99.99	MOhm Pass
Polarity	17/06/2013		Pass

Overall: Pass

Asset ID: 257	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	17/06/2013		Pass
Earth Current	17/06/2013	25	A Information
Earth	17/06/2013	0.04	Ohm Pass
Insulation	17/06/2013	>99.99	MOhm Pass
Polarity	17/06/2013		Pass

Detailed Test History



Test Status: All, Test Type: All
Person: All, Instrument: All
From: 11/06/2013 To: 10/06/2014

Overall: Pass

Asset ID: 258	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	17/06/2013		Pass
Earth Current	17/06/2013	25	A Information
Earth	17/06/2013	0.04	Ohm Pass
Insulation	17/06/2013	>99.99	MOhm Pass
Polarity	17/06/2013		Pass

Overall: Pass

Asset ID: 259	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	17/06/2013		Pass
Earth Current	17/06/2013	25	A Information
Earth	17/06/2013	0.04	Ohm Pass
Insulation	17/06/2013	>99.99	MOhm Pass
Polarity	17/06/2013		Pass

Overall: Pass

Asset ID: 260	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	17/06/2013		Pass
Earth Current	17/06/2013	25	A Information
Earth	17/06/2013	0.04	Ohm Pass
Insulation	17/06/2013	>99.99	MOhm Pass
Polarity	17/06/2013		Pass

Overall: Pass

Asset ID: 261	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	17/06/2013		Pass
Earth Current	17/06/2013	25	A Information
Earth	17/06/2013	0.04	Ohm Pass
Insulation	17/06/2013	>99.99	MOhm Pass
Polarity	17/06/2013		Pass

Overall: Pass

Asset ID: 262	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	17/06/2013		Pass
Earth Current	17/06/2013	25	A Information
Earth	17/06/2013	0.04	Ohm Pass
Insulation	17/06/2013	>99.99	MOhm Pass
Polarity	17/06/2013		Pass

Overall: Pass

Asset ID: 263	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	17/06/2013		Pass
Earth Current	17/06/2013	25	A Information
Earth	17/06/2013	0.04	Ohm Pass
Insulation	17/06/2013	>99.99	MOhm Pass
Polarity	17/06/2013		Pass

Overall: Pass

Asset ID: 264	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	17/06/2013		Pass
Earth Current	17/06/2013	25	A Information
Earth	17/06/2013	0.04	Ohm Pass
Insulation	17/06/2013	>99.99	MOhm Pass
Polarity	17/06/2013		Pass

Overall: Pass

Asset ID: 265	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	17/06/2013		Pass
Earth Current	17/06/2013	25	A Information
Earth	17/06/2013	0.04	Ohm Pass
Insulation	17/06/2013	>99.99	MOhm Pass
Polarity	17/06/2013		Pass

Detailed Test History



Test Status: All, Test Type: All
Person: All, Instrument: All
From: 11/06/2013 To: 10/06/2014

Overall: Pass

Asset ID: 266	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	17/06/2013		Pass
Earth Current	17/06/2013	25	A Information
Earth	17/06/2013	0.04	Ohm Pass
Insulation	17/06/2013	>99.99	MOhm Pass
Polarity	17/06/2013		Pass

Overall: Pass

Asset ID: 267	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	17/06/2013		Pass
Earth Current	17/06/2013	25	A Information
Earth	17/06/2013	0.04	Ohm Pass
Insulation	17/06/2013	>99.99	MOhm Pass
Polarity	17/06/2013		Pass

Overall: Pass

Asset ID: 268	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	17/06/2013		Pass
Earth Current	17/06/2013	25	A Information
Earth	17/06/2013	0.04	Ohm Pass
Insulation	17/06/2013	>99.99	MOhm Pass
Polarity	17/06/2013		Pass

Overall: Pass

Asset ID: 269	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	17/06/2013		Pass
Earth Current	17/06/2013	25	A Information
Earth	17/06/2013	0.04	Ohm Pass
Insulation	17/06/2013	>99.99	MOhm Pass
Polarity	17/06/2013		Pass

Overall: Pass

Asset ID: 270	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	17/06/2013		Pass
Earth Current	17/06/2013	25	A Information
Earth	17/06/2013	0.04	Ohm Pass
Insulation	17/06/2013	>99.99	MOhm Pass
Polarity	17/06/2013		Pass

Overall: Pass

Asset ID: 272	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	17/06/2013		Pass
Earth Current	17/06/2013	25	A Information
Earth	17/06/2013	0.04	Ohm Pass
Insulation	17/06/2013	>99.99	MOhm Pass
Polarity	17/06/2013		Pass

Overall: Pass

Asset ID: 278	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	17/06/2013		Pass
Earth Current	17/06/2013	25	A Information
Earth	17/06/2013	0.04	Ohm Pass
Insulation	17/06/2013	>99.99	MOhm Pass
Polarity	17/06/2013		Pass

Overall: Pass

Asset ID: 279	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	17/06/2013		Pass
Earth Current	17/06/2013	25	A Information
Earth	17/06/2013	0.04	Ohm Pass
Insulation	17/06/2013	>99.99	MOhm Pass
Polarity	17/06/2013		Pass

Detailed Test History



Test Status: All, Test Type: All
Person: All, Instrument: All
From: 11/06/2013 To: 10/06/2014

Overall: Pass

Asset ID: 280	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	17/06/2013		Pass
Earth Current	17/06/2013	25	A Information
Earth	17/06/2013	0.04	Ohm Pass
Insulation	17/06/2013	>99.99	MOhm Pass
Polarity	17/06/2013		Pass

Overall: Pass

Asset ID: 281	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	17/06/2013		Pass
Earth Current	17/06/2013	25	A Information
Earth	17/06/2013	0.04	Ohm Pass
Insulation	17/06/2013	>99.99	MOhm Pass
Polarity	17/06/2013		Pass

Overall: Pass

Asset ID: 282	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	17/06/2013		Pass
Earth Current	17/06/2013	25	A Information
Earth	17/06/2013	0.04	Ohm Pass
Insulation	17/06/2013	>99.99	MOhm Pass
Polarity	17/06/2013		Pass

Overall: Pass

Asset ID: 283	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	17/06/2013		Pass
Earth Current	17/06/2013	25	A Information
Earth	17/06/2013	0.04	Ohm Pass
Insulation	17/06/2013	>99.99	MOhm Pass
Polarity	17/06/2013		Pass

Overall: Pass

Asset ID: 284	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	17/06/2013		Pass
Earth Current	17/06/2013	25	A Information
Earth	17/06/2013	0.04	Ohm Pass
Insulation	17/06/2013	>99.99	MOhm Pass
Polarity	17/06/2013		Pass

Overall: Pass

Asset ID: 285	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	17/06/2013		Pass
Earth Current	17/06/2013	25	A Information
Earth	17/06/2013	0.04	Ohm Pass
Insulation	17/06/2013	>99.99	MOhm Pass
Polarity	17/06/2013		Pass

Overall: Pass

Asset ID: 286	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	17/06/2013		Pass
Earth Current	17/06/2013	25	A Information
Earth	17/06/2013	0.04	Ohm Pass
Insulation	17/06/2013	>99.99	MOhm Pass
Polarity	17/06/2013		Pass

Overall: Pass

Asset ID: 287	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	17/06/2013		Pass
Earth Current	17/06/2013	25	A Information
Earth	17/06/2013	0.04	Ohm Pass
Insulation	17/06/2013	>99.99	MOhm Pass
Polarity	17/06/2013		Pass

Detailed Test History



Test Status: All, Test Type: All
Person: All, Instrument: All
From: 11/06/2013 To: 10/06/2014

Overall: Pass

Asset ID: 288	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	17/06/2013		Pass
Earth Current	17/06/2013	25	A Information
Earth	17/06/2013	0.04	Ohm Pass
Insulation	17/06/2013	>99.99	MOhm Pass
Polarity	17/06/2013		Pass

Overall: Pass

Asset ID: 289	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	17/06/2013		Pass
Earth Current	17/06/2013	25	A Information
Earth	17/06/2013	0.04	Ohm Pass
Insulation	17/06/2013	>99.99	MOhm Pass
Polarity	17/06/2013		Pass

Overall: Pass

Asset ID: 290	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	17/06/2013		Pass
Earth Current	17/06/2013	25	A Information
Earth	17/06/2013	0.04	Ohm Pass
Insulation	17/06/2013	>99.99	MOhm Pass
Polarity	17/06/2013		Pass

Overall: Pass

Asset ID: 291	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	17/06/2013		Pass
Earth Current	17/06/2013	25	A Information
Earth	17/06/2013	0.04	Ohm Pass
Insulation	17/06/2013	>99.99	MOhm Pass
Polarity	17/06/2013		Pass

Overall: Pass

Asset ID: 292	Description: EURO	User: USER 4	Test Instrument: Y42-0708
Test Type	Date	Result	Unit Status
Visual	17/06/2013		Pass
Earth Current	17/06/2013	25	A Information
Earth	17/06/2013	0.04	Ohm Pass
Insulation	17/06/2013	>99.99	MOhm Pass
Polarity	17/06/2013		Pass

Overall: Pass

Total Tests: 318